



Wolverine AFDRCBO Series LED Indication Status

Indication Type	LED Status (The following illustration shows one cycle)	Number of Cycles	Standby Mode
No Fault	Ever Bright	Continuous →	
Leakage Fault	Flash	30 Times →	
Series Arc Fault	Flash	30 Times →	
Parallel Arc Fault	Flash	30 Times →	
Over voltage Fault	Flash	30 Times →	
Self-testing Fault	Flash	Continuous →	
Note	LED indicates, white colour; Fault Indication 1.5 seconds for 30 cycles before entering standby mode.		